


BIOSHIELD® UV DISINFECTION STERILIZER

REPLACEMENT PARTS

Item	Part No.	Description	US List	Can. List
1	523035	50 Watt UV Lamp for Model #522935	163.60	196.58
1	523036	80 Watt UV Lamp for Model #522936	176.82	212.47
1	523037	120 Watt UV Lamp for Model #522937	203.35	244.35
1	523038	150 Watt UV Lamp for Model #522938 and #522945	185.71	223.15
2	523034	4-Pin Lamp Connector	4.48	5.38
7	523121	Black Retaining Nut	9.94	11.94
14	523039	Quartz Sleeve 22.25" for Model #522935	77.36	92.96
14	523040	Quartz Sleeve 38.25" for Model #522936	88.42	106.25
14	523041	Quartz Sleeve 50.75" for Model #522937	132.81	159.58
14	523042	Quartz Sleeve 65.00" for Model #522938 and #522945	110.53	132.81
15	523110	50 Watt UV Sterilizer Housing	740.81	890.16
15	523111	80 Watt UV Sterilizer Housing	776.24	932.73
15	523112	120 Watt UV Sterilizer Housing	802.15	963.86
15	523113	150 Watt UV Sterilizer Housing	1102.26	1324.48
KITS				
	523013	Air Relief Kit	302.66	363.68
	523032	Ballast Assembly for Model # 522935-522637	358.65	430.95
	523033	Ballast Assembly for Model # 522638	737.87	886.62
	523053	Ballast Assembly for Model # 522945	737.87	886.62
	523054	Quartz Sleeve Module - All Models (Includes Item # 9, 10, 11, 12,13)	196.62	236.26
	523122	Union Assembly for Models # 522935-522637 (2")	98.82	118.74
	523148	Union Assembly for Models # 522638-522945 (3")	327.25	393.22
	523031	Seal Kit - All Models (Includes Item # 8, 10, 11, 12, 16)	58.99	70.88



CALIFORNIA PROPOSITION 65 WARNING

⚠ **WARNING:** Cancer and Reproductive Harm.
 ⚠ **AVERTISSEMENT:** Peut Causer le Cancer et des Dommages au Système Reproducteur.
 ⚠ **ADVERTENCIA:** Cáncer y Daño Reproductivo.

www.p65warnings.ca.gov

PH 202114