



Procedure for Updating ScreenLogic 2 5.2 Build 738.0 Rel. (Released on 3/26/19)




Steps For Updating ScreenLogic 2

Uninstall existing ScreenLogic Connect


Go to Website <u>www.pentair.com</u> – new software


Update Protocol Adapter


Update Interface Device(s)


































Steps For Updating ScreenLogic 2


Uninstall existing ScreenLogic Connect


Go to Website www.pentair.com – new software




























Steps For Updating ScreenLogic 2

Uninstall existing ScreenLogic Connect

Go to Website <u>www.pentair.com</u> – new software

Update Protocol Adapter



Update Protocol Adapter


VERY IMPORTANT:


Disable your computers wireless connection


Connect your laptop directly to the same router as your protocol adapter with an ethernet cable


You may need to ask the home owner to show you where the router is located (Multiple Routers?)























Steps For Updating ScreenLogic 2


Uninstall existing ScreenLogic Connect


Go to Website www.pentair.com – new software


Update Protocol Adapter


Update Interface Device(s)

























You're Finished

Updates are complete